



# LIFE PAINT

PRODUCT SPECIFICATIONS




## WATERPROOFING

### LIFE DECK WALL TO DECK DETAIL

The #1 cause for leaks on decks is the lack of proper flashing, followed by lack of slope, and then improperly applied deck coatings. To help illustrate the flashing problem, we have prepared the following drawings for your information. Please share this with your contractor, framer, stucco-contractor, architect or anyone else you feel could benefit for this information.

**DRAWING NOT TO SCALE**



Subsurface must meet local building codes. Minimum of 5/8" exterior plywood, T & G (or all seams blocked) with 1" in 4' of slope. Concrete over plywood must be at least 1-1/2"-2" thick.

